




EzLog™

From Petramode Limited

Visit www.petramode.com

The EASY and Professional Well Log Digitising and QC System

"Let your log curve data join the billions of curve-metres digitised or QC'd by EzLog worldwide".

Automatic Digitising

Manual, computer-aided and full multi-curve automatic digitising of black and white or colour prints

+ Overlay-synchro QC =

'Distorted' overlay and simultaneous synchronised side by side on-screen QC display

Your Well Logs sorted

Full control over your well log data.

Take control of your well log header and curve data with the worlds premier PC-based Well Log management system.

EzLog Features:

Quality Control:

- Display any LAS file - up to 32 curves on up to 16 tracks
- Fully configurable track layout
- Fully configurable curve layout
- Overlay of grid and curves onto raster scan of log print
- Full range of curve scale parameters, including linear/logarithmic/reciprocal
- Full support for curve backup (scale overflow) with 16 scales for each curve
- Dual synchronised window QC display of overlay and synthetic plot
- Check plot output to plotter, printer or file

Digitising:

- Manual digitising in freehand or point-to-point modes
- Computer-assisted automatic digitising
- Fully automatic multi-curve tracking with colour, thickness, coding and crossover detection also extent limit and digitised curve subtraction options
- Automatic and manual backup resolution functions

Data Management:

- LIS import and export
- Full range of curve transform functions including erase/constant/shift/order/exchange
- Correction of curve digitised to the wrong scale
- Smoothing filter
- Depth shift/stretch/squeeze
- Add or remove curve(s)
- Curve copy/cut/paste
- Curve resample
- Full LAS header editing plus import and export
- Connection to database with curve limit check, default layout and header validation and correction functionality
- Free viewer available for your partners/clients
- Compatible with WebDataView (www.webdataview.com) for web-based log viewing and remote QC

Give your well log data the valet service with EzLog

(See over for screen images)



Visit www.petramode.com

Petramode Limited

Tel +44 (0)20 8541 0090

E-mail info@petramode.com

Vector on Raster overlay
for easy vectorising and
precise quality control



Curve Transform

CURVE 2 CALI[IN] Cancel Go

From Depth: 2750 m To Depth: 2850 m

Import Simple Backup Scale Process Depth +/- Export

☐ Erase ☐ Constant ☐ Value Shift ☐ Pixel Shift

☐ Order left ☐ Order right with 2 CALI[IN]

☐ Copy to ☐ Exchange ☒ by pixels

☐ Invert value when copying: (1 / 1) * %

Full range of data transfer options

On-screen QC plot

Simultaneous, synchronised
display of overlaid vector
on raster and QC plot with
both windows independently
configurable and editable

